

# Oil Field Environmental Incident Summary

**Incident:** 20140927161330

**Date/Time of Notice:** 09/27/2014 16:13

**Responsible Party:** CONTINENTAL RESOURCES, INC.

**Well Operator:** CONTINENTAL RESOURCES, INC.

**Well Name:** SUNNY SLOPE CTB

**Field Name:** CEDAR HILLS

**Well File #:**

**Date Incident:** 9/27/2014

**Time Incident:** 09:08

**Facility ID Number:** 413779-07

**County:** BOWMAN

**Twp:** 131

**Rng:** 107

**Sec:** 14

**Qtr:** NE NE

**Location Description:**

**Submitted By:** Shane Knuchel

**Received By:**

**Contact Person:** Shane Knuchel  
PO BOX 268870  
OKLAHOMA CITY, OK 73126

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Tank Leak

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	10	Barrels	10	Barrels	10	barrels

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 12/28/2016

**Clean Up Concluded:** 9/30/2014

**Risk Evaluation:**

None

**Areal Extent:**

***Potential Environmental Impacts:***

Well site soil

***Action Taken or Planned:***

Tank was drained, gasket will be replaced. Standing oil was recovered and soil will be scraped up and taken to disposal.

***Wastes Disposal Location:*** Standing oil was recovered back to the tanks. Effected soil will disposed of at Petro comp disposal.

***Agencies Involved:***

***Updates***

---

***Date:*** 9/29/2014    ***Status:*** Reviewed - Assigned to Other Agency

***Author:*** Roberts, Kris

***Updated Oil Volume:***

***Updated Salt Water Volume:***

***Updated Other Volume:***

***Updated Other Contaminant***

***Notes:***

Release, due to a tank leak, remained on location within the diking according to the report. NDIC retains oversight.